

Government of West Bengal Office Of The Director General West Bengal Fire & Emergency Servicer 13D, Mirza Ghaliti Street, Kolketa - 16

Memo no.:IND/WB/FES/20182019/21173

Date: 04-06-2021

From: Divisional Fire Officer Fire Prevention Wing, West Bengal Fire & Emergency Services

To: Barasat Indira Gendhi Memorial High School 18, Jessore Rood, Rathtala (South) Barasat, North 24 Parganas, Kolkata 700124

Sub: Renewal of Fire Safety Certificate in favour of an Existing Construction of B+G+4 and G+3 storied building under Group Educational building (Darasat Indra Candhi Memorial High Echool) situated at the premises No.-18, Jeasone Roce, Rehitals(South) Borasat, 479(sh); Noister-7012-15.

This is in reference to your application no. 012515/211/100166 dated 12-06-2021 regarding the Renewal of Fire Safety Certificate in lawour of an Existing Construction of E4-044 and 043 aboned building under Group Educational building (Sersass linds Ganch Memorial High School) cituated at the premises No. 18, Jessore Road, Rathala(South) Barsest 24Pgs(N), Kolkata-700124

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found satisfactority working condition; in view of the above this office is releasing the Renewal of Fire Safety Certificate for occupancy of the attressed building.

However to up-keep: the Fire Safety Measure of the aforexaid building the following safety measures need to be inorporated? markstaned.

Recommendations

- However to up-keep the Fire Safety Measures, the following safety measures need to be incorporated and maintained.—

 1. Dineway must be free of any obstruction for easy movement of Fire Appliances. No Parking will be allowed in the Drive Way.
- The Interior finish decoration of building shall be made with low fisme spread material conforming to the I.S. Seedication.
- 3.To eliminate of fire hazard, Good Housekeeping both inside and outside of the building shall be strictly maintained.

The authoritis of the four-rest can be winfed by accessing the LPC, administrating as and then solding on the Verification of Digitary Signal Decument for any keyling in the Unique Number 1973/97 CF1500768.

Page 7.

For secure paperiess sol

- Existing electrical wring of the entire building shall have to be carefully checked for any wear and teer in them, ancularly line above take ceiling & ducts.
- . The Exit Sign and fire notice shall be maintained from facing and dust sedimentation and precered and displayed at all expectable place.
- i. The amployees and Security staffs shall be conversant with installed Fire Fighting Equipments of the building and sperate in the event of fire and testing.
- 7.Mock Fire Practice and Evacuation Drill shall be performed periodically with participation of all the occupant of the building and same has to be informed to the local Fire Station positively.
- 6.Special training to employees and staffs shall be give for carrying the ambulent(s). To the safer place in the event of any exigency.

 9.Meter and Main room shall be removed to outside of the building and be protected with CO2 or D.C.P. Moduler Fire
- Extinguishers.
- 10 A Crew of trained fireman under an experienced officer shall be maintained round the clock for safety of the building and its occupants.
- 11 Fire License shall have to be obtained for storing and/processing with LPG and/ other highly inflammable articles.
- 12. Arrangement shall have to be made for regular enecking, setting and meintenence of all the fire fighting installation in the building to keep them in perfectly good condition at all the time.

 13. If required the old electrical lines shall have to be replaced with new ones in M. S. conduit (aying continuously bonded
- to the earth.
- 14 Periodical flashing of water from the Landing valve and First Ald Fire Fighting Equipment shall be made to maintain the efficiency working performance of the Fire Fighting System Installed.
- 15.The Fire Safety Audit to be conducted at a regular interval and to be recorded in the Fire Prevention Maintenance Register.
- 16 At an interval of every six month, a report relating to the good working condition of the fire fighting installation and detection system and all electrical installation shall have to submit to the nearest Fire Stallon.
- 17. Revised Fire Safety Recommendation is to be obtained for change of occupancy in basement and serrace of G+3 storied building a period of six month from the issuance of this letter.
- from the issuance of this letter.
- 19 Failing which as mentioned in Para 17 & 18, this certificate will be treated as cancelled and in the mean time if any untoward incident takes place, the school authority shall be held responsible for the same.
- The subsectory of the document can be restrictly as associated by associated built, educated gavin and then decorate the "enforcing of Digitals Signed Decorated bits and keying a things in Number 2013 TO 2015 DIGITAL Signed Signed Decorated bits and keying a things in Number 2013 TO 2015 DIGITAL Signed Signed Decorated bits and keying a things in Number 2013 TO 2015 DIGITAL SIGNED SIG

his Renewal of Fire Safety Conflicate is valid for 3 years and his to be renewed on compliance with conditions taid down Fire 17 & 18 within the slipulated period

> Signature Rigit Verified Dignally signal for SAACLI KUNAAR SASS of Date: 2021 40 34 20 28 20 10

Divisional Fire Officer
West Bengal Fire & Emergency Services